

VEHICLE INSPECTION REPORT

BF18TFJ

Iveco Daily 35-120

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Location Doncaster

Reg. date 19/03/2018

Year 2018

Mileage 85,005 Miles
Warranted

Fuel Type DIESEL

GVW 3500kg

Colour WHITE

VIN ZCFC1358705203182

Body Style Panel Van MWB

Service history None

MOT Due 02/06/2027

CAP Clean £4,250.00

CAP Average £3,600.00

CAP Below £2,750.00

Gearbox MANUAL

Gears 6

SIDE LOAD DOOR, AD-BLUE, WB 4100

Tyres

NSF

NSR

OSF


OSR





Spare

Features

- Bluetooth connection
- Air conditioning
- Central locking
- Park assist camera
- Front electric windows
- Cloth seat trim
- Rear parking sensor
- Drivers airbag
- Digital radio
- Passenger airbag


Photos







Condition Check




Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Panel Front
Cracked
Replace




3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

4: Door nsf
Scratched
Over 25mm Thru Paint



5: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm

6: Qtr Panel nsr
Dented
With Paint Damage



7: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm

8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm

10: Qtr Panel nsr
Dented
Over 30mm




11: Door nsr
Dented
Over 30mm

12: Door osr
Dented
Over 30mm



13: Carpets Front
Holed
Over 3mm

14: Seat Base Cover osf
Holed
Over 3mm



15: Seat Base Cover nsf
Soiled
Heavy

16: Glove Box Lid
Broken
Replace

Interior

Carpet Condition	Poor
Seat Condition	Poor

Upholstery Condition	Poor
Odour	No