

VEHICLE INSPECTION REPORT

SV70MKF

Daf XF 530

Non Runner

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 12/11/2020

VIN XLRTGH4300G330002

Axle Combi 6x2

Year 2020

Body Style Tractor Unit

Steering Combi Mid-Lift Steer

Mileage Not Showing

MOT Due 31/05/2026

Rear Suspension Air

Fuel Type Diesel

Cab Type SUPER SPACE CAB

Colour WHITE

Gearbox AUTOMATIC

NON-RUNNER, TURNS OVER WONT START SLIDING 5TH WHEEL, MOT SHOWS 765,358KM 08/05/2025

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2


OSO3

OSO4


Features

- Radio/CD
- Air conditioning

Photos



Condition Check



Damage Photos



1: Door Moulding of
Scratched (Painted)
Over 25mm Thru Paint




2: Bumper Front
Rusted
Over 5mm



3: Door osf
Dented
Over 30mm



4: Door nsf
Dented
2 Or Less UpTo 10mm



5: Wing nsf
Cracked
Replace

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs		Fault	Gearbox 1st and Reverse Test	Fault
Brakes		Fault	Clutch Slip Test from Static	Fault
Turbo Boosting		Fault	Gearbox Static Gear Selection (engine running)	Fault
Parking Brake		Fault	No Excessive Smoking	Fault
EML light illuminated		Fault	Oil warning light illuminated	Fault
Airbag light illuminated		Fault	Service indicator light illuminated	Fault
ABS light illuminated		Fault		

Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	Fault